

## Sure Klean® Fireplace Cleaner Cleaning Specification

*Specifier Note: The information provided below is intended to guide the Architect in developing specifications for products manufactured by PROSOCO, Inc. and should not be viewed as a complete source of information about the product(s). The Architect should always refer to the Product Data Sheet and MSDS for additional recommendations and for safety information*

*Specifier Note: Paragraph below is for PART 1 GENERAL, Quality Assurance.*

### Test Area

Test a minimum 4 ft. by 4 ft. area on each type of masonry. Use manufacturer's application instructions. Let the test panel dry 3 to 7 days before inspection. Keep test panels available for comparison throughout the cleaning project.

*Specifier Note: Paragraphs below are for PART 2 PRODUCTS, Manufacturers and Products.*

**Manufacturer:** PROSOCO, Inc., 3741 Greenway Circle, Lawrence, KS 66046. Phone: (800) 255-4255; Fax: (785) 830-9797. E-mail: [CustomerCare@prosoco.com](mailto:CustomerCare@prosoco.com)

### Product Description

Sure Klean® Fireplace Cleaner is a nonacidic detergent formulated to remove dirt, smoke and carbon staining from brick and stone fireplaces. Dissolved surface staining is easily washed away with low-volume water or wet sponge.

### Technical Data

FORM: Clear liquid

SPECIFIC GRAVITY: 1.094

FLASH POINT: 127 degrees F (53 degrees C)

FREEZE POINT: 25 degrees F (-4 degrees C)

WT./GAL.: 9.1 lbs.

pH: 9.4

### Limitations

- Not suitable for application to metal or painted surfaces.
- May not be suitable for polished marble.

*Specifier Note: Paragraphs below are for PART 3 EXECUTION, Installation.*

### Application

Before applying, read "Protect" and "Precautionary Measures" sections in the Manufacturer's Product Data Sheet for Fireplace Cleaner. Do not dilute or alter.

1. Lightly prewet surface with clean water.
2. Spray or brush apply cleaning solution.
3. Let cleaner stand for 2-3 minutes. Don't let cleaner dry on the surface.
4. Reapply cleaner to heavily soiled areas. Using a soft-fibered scrubbing brush, gently agitate areas of severe soiling.
5. Rinse treated surfaces with clean water. If using a sponge, change rinse water frequently.